





THE MEANING OF ZETACORE PROCESS

ZAITEX R&D Garment team fine-tuned a stunning dyeing process called **ZETACORE**.

It has been designed to fully **optimize** the most crucial steps in **garment dyeing & finishing**.

ZETACORE gives the chance to take advantage of the great features of a **selected bundle of dyes and auxiliaries** to create **infinite fashion effects** while effectively **saving time**, **energy and water**.

Such innovative process is focused on innovating the traditional production steps by improving the following:

- · water consumption with short liquor ratio
- water treatment with no or less salt required for the dyeing
- energy consumption thanks to low dyeing temperature
- · overall fastness results

ZETACORE Process is a great step ahead in the world ofgarment production, designed to let garment makers have no limits in creating new fashion trends.

The dyes and auxiliaries involved in **ZETACORE Process** are GOTS, ZDHC and bleusign approved.







ZDHC MRSL v3.1




bluesign approved

EVERSAVE APPROACH

ZETACORE Process belongs to ZAITEX's eco-friendly project called **EVERSAVE**: our approach to lead our customers to an effective **innovation** through the **optimization** of garment dyeing & finishing process.

ZETACORE Process has a great goal: **lowering the environmental impact** by improving fundamental steps in garment treatment and giving effective solutions to save water, time and energy.








ZAITEX

MAIN FEATURES OF ZETACORE VINTAGE HI-LOW DYEING

- VINTAGE HI-LOW EFFECT
- > GOOD OVERALL FASTNESS
- LESS ENERGY CONSUMPTION (50°C)
- > SHORT TIME PROCESS
- LESS SALT REQUIRED
- > LESS WATER TREATMENT

THE DYEING METHOD IN DETAIL





	STEP	ZAITEX PRODUCTS	DESCRIPTION				
1	CATIONIZATION	ZETAREACT CDF 200	Resin treatment for a surface dyeing and marked vintage look effect				
2	DYEING	SELECTION OF ZETAREACT DYES	Dyeing at 50°C for 30′ ~ 45′				
3	NEUTRALIZATION	Acetic Acid	-				
4	SOAPING	ZETASOAP SLT	To improve fastnesses, it is recommended to carry out a soaping treatment				
5	FINISHING	-	Selection as per final look request. To increase vintage look effect it is recommended ZETALASE BT 30 or ZETAKIN DRY-0 NEW				






MAIN FEATURES OF ZETACORE WAVE DYEING

- > COLD PIGMENT LOOK
- > GOOD OVERALL FASTNESS
- LESS ENERGY CONSUMPTION (50°C)
- > SHORT TIME PROCESS
- NO SALT REQUIRED
- > LESS WATER TREATMENT

THE DYEING METHOD IN DETAIL



TREATMENT ZAITEX PRODUCTS			DESCRIPTION				
1	CATIONIZATION	ZETAREACT CDF 200	Resin treatment for a surface dyeing and marked build-up on the seams				
2 + 3	PRE SPIN + TUMBLER	-	At the end of the hydroextraction the material must remain damp, but not dripping (pick-up 100-150%)				
4	DYEING	SELECTION OF ZETAREACT DYES	Dyeing at 50°C for 30′ ~ 45′				
5	NEUTRALIZATION	Acetic Acid	-				
6	SOAPING	ZETASOAP SLT	To improve fastnesses, it is recommended to carry out a soaping treatment				
7	FINISHING	-	Selection as per final look request. To increase vintage look effect it is recommended ZETALASE BT 30 or ZETAKIN DRY-O NEW				






MAIN FEATURES OF ZETACORE FOG DYEING

- > GOOD OVERALL FASTNESS
- LESS ENERGY CONSUMPTION
- > ROOM TEMP DYEING WITH NEBULIZATION
- NO SALT REQUIRED
- LESS WATER TREATMENT

THE DYEING METHOD IN DETAIL



TREATMENT ZAITEX PRODUCTS			DESCRIPTION				
1	CATIONIZATION	ZETAREACT CDF 200	Resin treatment				
2	PRE SPIN	-	At the end of the hydroextraction the material must remain damp, but not dripping (pick-up 80~90%)				
3	DYEING	SELECTION OF ZETAREACT DYES	Dyeing at room temperature with fog/nebulizing systems				
4	NEUTRALIZATION	Acetic Acid	-				
5	SOAPING	ZETASOAP SLT	To improve fastnesses, it is recommended to carry out a soaping treatment				
6	FINISHING	-	Selection as per final look request. To increase vintage look effect it is recommended ZETALASE BT 30 or ZETAKIN DRY-0 NEW				



ZETACORE VINTAGE DYEING

ZETACORE WAVE DYEING

ZETACORE FOG DYEING

DISCHARGEABILITY

ZETACORE Process allows an extra layer of creativity by letting the dischargeability of garments with:

- ZETAOX DD alternative to Potassium Permanganate
- ZETAKIN DRY-0 NEW ozone enhancer
- POTASSIUM PERMANGANATE



DYES RANGE SELECTION & DISCHARGEABILITY RESULTS

	POTASSIUM PERMANGANATE	ZETAOX DD	OZONE SYSTEM		
Product q.ty:	30 g/I KMn04 + 1 g/I ZETAKIN PP	80%	ZETAKIN DRY-O NEW 5%		
Application:	Spray				
Drying:	no drying just hanging at room to	tumble drying + ozone treatment			
Neutralization:	2 g/l Sodium metabisulphite				

		NON TREATED	DISCHARGEABILITY WITH POTASSIUM PERMANGANATE	DISCHARGEABILITY WITH ZETAOX DD	DISCHARGEABILITY WITH OZONE SYSTEM
ZETAREACT YELLOW TE-2G	1%				
ZETAREACT YELLOW TE-R	1%				
ZETAREACT ORANGE TE-A 01	1%				
ZETAREACT RED TE-3B only for corrosion purpose	1%				
ZETAREACT RED TE-5B	1%				
ZETAREACT BORDEAUX L-BL	1%				
ZETAREACT TURQUOISE F-G	1%				



		NON TREATED	DISCHARGEABILITY WITH POTASSIUM PERMANGANATE	DISCHARGEABILITY WITH 100% ZETAOX DD	DISCHARGEABILITY WITH 0ZONE SYSTEM
ZETAREACT BLUE L-3B	1%				
ZETAREACT BLUE TE-G	1%				
ZETAREACT BLUE TE-RRN	1%				
ZETAREACT OLIVE PS	1%				
ZETAREACT NAVY BLUE L-BN	2%				
ZETAREACT GREY PS	1%				
ZETAREACT BLACK TE-SL	2%				
ZETAREACT BLACK TE-V	2%				

DISCHARGEABILITY EXAMPLES

DISCHARGE WITH POTASSIUM PERMANGANATE DISCHARGE WITH ZETAKIN DRY-O NEW DISCHARGE WITH ZETAOX DD

FASTNESS RESULTS



		UNI EN ISO 105-C06:A1S WASHING AT 40°C				SUN TEST		
		AC	СО	PA	PES	PAC	wo	24 - 48h
	ZETAREACT YELLOW TE-2G	5	5	5	5	5	5	3-4
	ZETAREACT YELLOW TE-R	5	5	5	5	5	5	4
	ZETAREACT ORANGE TE-A 01	5	5	5	5	5	5	3-4
THOSE	ZETAREACT RED TE-3B only for corrosion purpose	5	5	5	5	5	5	2-3
	ZETAREACT RED TE-5B	5	5	5	5	5	5	2-3
	ZETAREACT BORDEAUX L-BL	5	5	5	5	5	5	4
	ZETAREACT TURQUOISE F-G	5	3-4 /4	5	5	5	4-5	3-4
	ZETAREACT BLUE L-3B	5	3-4/4	5	5	5	5	4
	ZETAREACT BLUE TE-G	5	5	5	5	5	5	4
	ZETAREACT BLUE TE-RRN	5	4	5	5	5	5	4
	ZETAREACT OLIVE PS	5	5	5	5	5	5	4
	ZETAREACT NAVY BLUE L-BN	5	5	5	5	5	5	3
	ZETAREACT GRAY PS	5	4-5	5	5	5	5	4
	ZETAREACT BLACK TE-SL	5	5	5	5	5	5	2-3
	ZETAREACT BLACK TE-V	5	4	5	5	5	5	2-3





zaitexfashion.com





Warnings: the information and recommendations presented here were written with the utmost care, but they can't be extended to cover every possible $case. \ They have to be intended as non-binding guidelines and must be adapted to the process condition. \ The product-whether used singly or in combination$ $with other substances - should undergo \ lab \ tests \ prior \ to \ bulk \ production. \ Our \ Company \ can \ not \ be \ held \ responsible \ for \ any \ negative \ results. \ The \ Customers$ take on full responsibility regardless of the result they are going to get.